

OUT58781

S E C R E T 131533Z CITE [] 7447

036 JUN 13 15 45Z

25X1

25X1

1. CAMERA B-7 WAS USED IN MISSION 8099 FLOWN ON 10 JUNE 1966. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: A MINUS DENSITY LINE, 1.4 INCHES IN LENGTH IS PRESENT ON EVERY FRAME OF THE MISSION. THE LINE IS ORIENTED PERPENDICULAR TO THE MAJOR AXIS OF THE FILM AND ITS CENTER IS LOCATED 1.25 INCHES FROM THE TITLED EDGE OF THE FILM AND WITHIN THE FORMAT 0.65 INCHES FROM THE NON-DATA BLOCK END OF THE FRAME. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 0673 AND HEAT SPLICES ARE LOCATED BETWEEN 0901/0902, 1208/1209, AND IN FRAME 8024.

C. 9L SIDE: MINOR STATIC TRACES ARE PRESENT ON BOTH FILM EDGES THROUGHOUT THE MISSION. CREASES, INDENTED FROM THE EMULSION SIDE, ARE PRESENT ON THE FOLLOWING FRAMES: 1111 THROUGH 1114, 1203 THROUGH 1207, AND 1257 THROUGH 1268. ASSOCIATED WITH THE CREASES ARE PLUS AND MINUS DENSITY STREAKS. A BREAKDOWN SPLICE WAS MADE IN FRAME 711.

D. BOTH SIDES: SEVERAL FRAMES ARE SMEARED DUE TO VEHICLE MANEUVERS. A SLIGHT FALL OFF OF IMAGE QUALITY OCCURS NEAR THE DATA CHAMBER ENDS OF EACH FRAME. THE DATA CHAMBER WAS NOT EXPOSED ON FRAME 1671. THE DATA CHAMBER FRAME COUNTER JUMPED ONE UNIT BETWEEN TITLED FRAMES 0001 AND 0002. THE FRAMES ARE TITLED CONSECUTIVELY.

13 JUN 1966

DISTRIBUTION		
Cy No.	Office	Action
1	File	
	OS	
	ADMIN	
	SEC BR	
	P & DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
	TID 3/45	
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-10	
	DIA-AP	

SECRET

TIVELY 0001 THROUGH 1675.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS AND HAZE DEGRADE APPROXIMATELY 30 PERCENT OF THE MISSION.

S E C R E T

/END OF MESSAGE/

1